

1		2		3	4	5	6	7	8	
High photosynthesis (H)		The female seat height (H1)	The male seat height (H2)	Insertion height (H3)		REV	ECN	DESCRIPTION	MDF' D	DATE
4.0		3.0	1.0	1.9		1.0	/	新发行		2021-07-08
4.5		3.5	1.0	1.9						
5.0		3.0/4.0	2.0/1.0	1.9						
5.5		3.5/4.5	2.0/1.0	1.9						
6.0		4.0	2.0	1.9						
6.5		4.5	2.0	1.9						
7.0		3.0	4.0	1.9						
7.5		3.5	4.0	1.9						
8.0		4.0	4.0	1.9						
8.5		4.5	4.0	1.9						

NO. of Contacts		Dimension (mm)				
		A±0.10	B±0.10	C±0.10	D±0.10	E±0.10
6		4.30	1.60	3.40	2.60	4.00
8		5.10	2.40	4.20	3.40	
10		5.90	3.20	5.00	4.20	
12		6.70	4.00	5.80	5.00	
14		7.50	4.80	6.60	5.80	
16		8.30	5.60	7.40	6.60	
18		9.10	6.40	8.20	7.40	
20		9.90	7.20	9.00	8.20	
22		10.70	8.00	9.80	9.00	
24		11.50	8.80	10.60	9.80	
26		12.30	9.60	11.40	10.60	8.00
28		13.10	10.40	12.20	11.40	
30		13.90	11.20	13.00	12.20	
32		14.70	12.00	13.80	13.00	
34		15.50	12.80	14.60	13.80	
36		16.30	13.60	15.40	14.60	
38		17.10	14.40	16.20	15.40	
40		17.90	15.20	17.00	16.20	
42		18.70	16.00	17.80	17.00	
44		19.50	16.80	18.60	17.80	
46		20.30	17.60	19.40	18.60	
48		21.10	18.40	20.20	19.40	
50		21.90	19.20	21.00	20.20	
52		22.70	20.00	21.80	20.80	
54		23.50	20.80	22.60	21.80	
56		24.30	21.60	23.40	22.60	
58		25.10	22.40	24.20	23.40	
60		25.90	23.20	25.00	24.20	
62		26.70	24.00	25.80	25.00	
64		27.50	24.80	26.60	25.80	
66		28.30	25.60	27.40	26.60	
68		29.10	26.40	28.20	27.40	
70		29.90	27.20	29.00	28.20	
72		30.70	28.00	29.80	29.00	
74		31.50	28.80	30.60	29.80	
76		32.30	29.60	31.40	30.60	
78		33.10	30.40	32.20	31.40	
80		33.90	31.20	33.00	32.20	
82		34.70	32.00	33.80	33.00	
84		35.50	32.80	34.60	33.80	
86		36.30	33.60	35.40	34.60	
88		37.10	34.40	36.20	35.40	
90		37.90	35.20	37.00	36.20	
92		38.70	36.00	37.80	37.00	
94		39.50	36.80	38.60	37.80	
96		40.30	37.60	39.40	38.60	
98		41.10	38.40	40.20	39.40	
100		41.90	39.20	41.00	40.20	

ASSEMBLY

Diagram showing dimensions A, B, C, D, E, and COVER. Dimensions are given in mm.

Diagram showing dimensions 1.25, 2.00, 6.00, 0.80, 0.30, and B. Dimensions are given in mm.

P.B.C LAYOUT

Diagram showing dimensions 5.20±0.10, 12±0.08, H3, 1.90, and 4.10. Dimensions are given in mm.

Diagram showing dimensions 0.80±0.10, 0.25, and 2-Ø0.50. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

Diagram showing dimensions 0.80, 0.30, and B. Dimensions are given in mm.

<